



Brandeis University

Application for Demolition Delay Determination by the Waltham Historical Commission

Usen Castle –Existing Conditions Photos

2/23/2016



**View of Tower A and Tower B
from Brandeis Campus Loop Road**

Slide #2



**View of Tower A and Tower B
from Brandeis Campus Loop Road**

Slide #3



**View of Tower A and Tower B
from Brandeis Campus Loop Road**

Slide #4



**View of Tower B
from Brandeis Campus Loop Road**



**View of Tower A and Tower B
from South Street**



**View of Tower A and Tower B from
South Street**



**View of Tower A and Tower B
from South Street at Campus entrance**



**View of protective netting at parapet, scaffolding
at walkways & rooftop fire escape at Tower A and Tower B**

Slide #9



**View of scaffolding protection
at courtyard entry**