

View of protective scaffolding in courtyard

Slide #11



View of fire escape and protective scaffolding at Tower B



View of rooftop fire escape at Tower A



View of added bracing and protective netting at Tower A roof




View of rooftop fire escapes at Tower B




View of added bracing and protective netting at Tower A roof

Slide #16



View of protective scaffolding at Schwartz Hall walkways


Slide #17



View of protective scaffolding at Tower A walkway



View of exploratory opening to expose make-up of structural wall at Tower B



View of protective Slice scaffolding at Schwartz Hall entry

Slide #20